

5 in 1, 6 in 1 SERIES
Photo tach., Contact tach.
Stroboscope, Type K Temp.
IR Temp. adapter



**+ Type K Temp., Pt 1000 ohm
TACHOMETER/STROBOSCOPE**

Model : DT-2336

- * Multi-functions, one meter combine :
 1. Photo tachometer
 2. Contact Tach. (RPM, m/min., ft/min.).
 3. Digital Stroboscope
 4. Type K Temp. (optional Temp. probe)
 5. Pt 1000 ohm Temp. (optional Temp. probe)
- * High intensity white LED light beam for photo tachometer, safety and save the power energy.
- * Photo Tach. : 5 to 100,000 RPM
- * Contact Tach. : 0.5 to 19,999 RPM.
- * Surface speed : m/min, ft/min.
- * Digital Stroboscope : 100 to 100,000 FPM/RPM
- * Type K Thermometer (optional type K probe) : -100 to 1300 °C, °C/°F.
- * Pt 1000 Thermometer (optional Pt probe) : -10.0 to 70.0 °C, °C/°F.
- * Hold button, REC (Max./Min) button.
- * Back housing with Tripod Fix Nut.
- * USB/RS232 computer interface
- * Power : '1.5 V AA (UM-3) battery x 4 PCs
- * Optional type K Temp. probes : TP-01, TP-02A, TP-03, TP-04, TP-05.
- * Optional Pt 1000 ohm Temp. probe : TP-1000.
- * With tripod fix nut.



**+ Type K Temp., Pt 1000 ohm Temp.
IR Temp. adapter**

TACHOMETER/STROBOSCOPE

Model : DT-2436

- * Multi-functions, one meter combine :
 1. Photo tachometer.
 2. Contact Tach. (RPM, m/min., ft/min.).
 3. Digital Stroboscope.
 4. Type K Temp. (optional Temp. probe)
 5. Pt 1000 ohm Temp. (optional Temp. probe)
 6. Infrared Temp. (optional IR adapter)
- * High intensity white LED light beam for photo tachometer, safety and save the power energy.
- * Photo Tach. : 5 to 100,000 RPM
- * Contact Tach. : 0.5 to 19,999 RPM.
- * Surface speed : m/min, ft/min.
- * Digital Stroboscope : 100 to 100,000 FPM/RPM.
- * Type K Thermometer (optional type K probe) : -100 to 1300 °C, °C/°F.
- * Pt 1000 Thermometer (optional Pt probe) : -10.0 to 70.0 °C, °C/°F.
- * Pt 1000 Thermometer (optional Pt probe) : -10.0 to 70.0 °C, °C/°F.
- * IR Thermometer (optional IR adapter) : -30 to 305 °C, °C/°F.
- * Hold button, REC (Max./Min) button.
- * Back housing with Tripod Fix Nut.
- * USB/RS232 computer interface.
- * Power : '1.5 V AA (UM-3) battery x 4 PCs
- * Optional type K Temp. probes : TP-01, TP-02A, TP-03, TP-04, TP-05.
- * Optional Pt 1000 ohm Temp. probe : TP-1000.
- * Optional IR (infrared) Temp. adapter : IR-36.
- * With tripod fix nut.