

**5 in 1, 6 in 1** SERIES  
**Photo tach., Contact tach.**  
**Stroboscope, Type K Temp.**  
**IR Temp. adapter**



**+ Type K Temp., Pt 1000 ohm TACHOMETER/STROBOSCOPE**

**Model : DT-2336**

- \* Multi-functions, one meter combine :
  1. Photo tachometer
  2. Contact Tach. ( RPM, m/min., ft/min. ).
  3. Digital Stroboscope
  4. Type K Temp. ( optional Temp. probe )
  5. Pt 1000 ohm Temp. ( optional Temp. probe )
- \* High intensity white LED light beam for photo tachometer, safety and save the power energy.
- \* Photo Tach. : 5 to 100,000 RPM
- \* Contact Tach. : 0.5 to 19,999 RPM.
- \* Surface speed : m/min, ft/min.
- \* Digital Stroboscope : 100 to 100,000 FPM/RPM
- \* Type K Thermometer ( optional type K probe ) : -100 to 1300 °C, °C/°F.
- \* Pt 1000 Thermometer ( optional Pt probe ) : -10.0 to 70.0 °C, °C/°F.
- \* Hold button, REC ( Max./Min ) button.
- \* Back housing with Tripod Fix Nut.
- \* USB/RS232 computer interface
- \* Power : '1.5 V AA ( UM-3 ) battery x 4 PCs
- \* Optional type K Temp. probes : TP-01, TP-02A, TP-03, TP-04, TP-05.
- \* Optional Pt 1000 ohm Temp. probe : TP-1000.
- \* With tripod fix nut.



**+ Type K Temp., Pt 1000 ohm Temp. IR Temp. adapter TACHOMETER/STROBOSCOPE**

**Model : DT-2436**

- \* Multi-functions, one meter combine :
  1. Photo tachometer.
  2. Contact Tach. ( RPM, m/min., ft/min. ).
  3. Digital Stroboscope.
  4. Type K Temp. ( optional Temp. probe )
  5. Pt 1000 ohm Temp. ( optional Temp. probe )
  6. Infrared Temp. ( optional IR adapter )
- \* High intensity white LED light beam for photo tachometer, safety and save the power energy.
- \* Photo Tach. : 5 to 100,000 RPM
- \* Contact Tach. : 0.5 to 19,999 RPM.
- \* Surface speed : m/min, ft/min.
- \* Digital Stroboscope : 100 to 100,000 FPM/RPM.
- \* Type K Thermometer ( optional type K probe ) : -100 to 1300 °C, °C/°F.
- \* Pt 1000 Thermometer ( optional Pt probe ) : -10.0 to 70.0 °C, °C/°F.
- \* Pt 1000 Thermometer ( optional Pt probe ) : -10.0 to 70.0 °C, °C/°F.
- \* IR Thermometer ( optional IR adapter ) : -30 to 305 °C, °C/°F.
- \* Hold button, REC ( Max./Min ) button.
- \* Back housing with Tripod Fix Nut.
- \* USB/RS232 computer interface.
- \* Power : '1.5 V AA ( UM-3 ) battery x 4 PCs
- \* Optional type K Temp. probes : TP-01, TP-02A, TP-03, TP-04, TP-05.
- \* Optional Pt 1000 ohm Temp. probe : TP-1000.
- \* Optional IR ( infrared ) Temp. adapter : IR-36.
- \* With tripod fix nut.